

Internal
M/011/0003



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program August 10, 2010

Reviewed: 

Mine Name: UDOT Beck Street Quarry	Permit Number: M/011/0003
Operator Name: Utah Dept of Transportation	Inspection Date: April 24, 2010
Inspector(s): L Heppler	Time: 11:00 am
Other Participants: none	Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>


Bond Renewal Date: 08-18-2011 **Bond Amount:** \$374,100

Purpose of Inspection: Routine annual Inspection. This site was inspected as a large mine site on 09/11/2007, no inspection report is noted in electronic file, but notes of the 09/11/2007 inspection are in the foxpro database.

Inspection Summary: Currently there is no mining at this site, but there is processing equipment at the base of the mine site. Every effort should be made to salvage top soil from the site prior to mining.

Photos were taken to document site conditions.

Conclusions and Recommendations: OGM to continue annual inspections and monitor the site when in the area.

Inspector's Signature 

LAH:vs

cc: Scott Nussbaum - UDOT

O:\M011-Davis\E0110001-UDOTBeckStreet\inspections\lnsp-04232010.doc





View towards base – Note Temporary crushing equipment on right center of photo (also note - base of adjacent mining permit)



Upper portion of Mine site - undisturbed